

PATENT
Attorney Docket No.: 13464US04

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Application of:

Esin Terzioglu, et al.

Patent No: 7,110,309

Issued: September 19, 2006

Serial No: 10/612,479

Filed: July 2, 2003

For: MEMORY ARCHITECTURE WITH
SINGLE-PORT CELL AND DUAL-
PORT (READ AND WRITE)
FUNCTIONALITY

CERTIFICATE OF TRANSMISSION

I hereby certify that this correspondence is
being transmitted via EFS-Web to the
United States Patent and Trademark Office
on November 14, 2006.

Michael T. Cruz

Michael T. Cruz
Reg. No. 44,636

REQUEST FOR CERTIFICATE OF CORRECTION UNDER §1.322(a)

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

Pursuant to 37 CFR §1.322(a), Applicants hereby request a Certificate of Correction to be issued for the above-identified U.S. Patent correcting the patent as noted in the attached "Certificate of Correction" form PTO 1050 (Rev. 2-93). Issuance of the Certificate of Correction is necessary in order to correct errors made by the U.S. Patent and Trademark Office ("PTO").

U.S. Patent No. 7,110,309 issued September 26, 2006
Request for Certificate of Correction Pursuant to
C.F.R. § 1.322(a) dated November 14, 2006


Specifically, the errors that need to be corrected are as follows:

Column 30, line 3 delete "pod" and insert --port--.
Column 30, line 10 delete "pod" and insert --port--.

No additional fees are believed due, but in the event that any additional fees are required for the filing of this request, the Commissioner is authorized to charge Deposit Account No. 13-0017, in the name of McAndrews, Held & Malloy, Ltd.

Respectfully submitted,

Dated: November 14, 2006



Michael T. Cruz
Registration No. 44,636
Attorney for Applicants

McANDREWS, HELD & MALLOY, LTD.
500 West Madison Street, 34th Floor
Chicago, Illinois 60661
Telephone: (312) 775-8000
Facsimile: (312) 775-8100

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO : 7,110,309

APPLICATION NO.: 10/612,479

DATED : September 19, 2006

INVENTOR(S) : Esin Terzioglu et al.

It is certified that error appears or errors appear in the above-identified patent and that
said Letters Patent are hereby corrected as shown below:

Column 30, line 3 delete "pod" and insert --port-- .
Column 30, line 10 delete "pod" and insert --port--.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

McAndrews, Held & Malloy
500 West Madison Street, 34th Floor
Chicago, IL 60661
(312) 775-8000 phone
(312) 775-8100 fax

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.